



# Recent Findings on Glass-Breakage

PV ModuleTech Europe – Malaga, Spain

Steven Xuereb, Executive Director

2 December 2025

# Kiwa PI Berlin: Trusted Solar and Storage Advisors




**1,000+**  
Factory Audits Conducted across PV Modules,  
BESS, Inverters and Transformers

**175+ GW**  
PV Production Capacity Evaluated

**20+ GW**  
Technical Advisor and Owner's Engineering Roles

**3 PV Labs in Key Markets**  
Germany, China, USA (PVEL)



Kiwa



Kiwa PI Berlin



PVEL



Extel Energy



Market Served by Kiwa

# Agenda

1. Factors leading to more glass breakage
2. Factory findings
3. Lab tests and findings
4. Field findings
5. Summary of potential causes
6. Action plan for the industry





# Factors Leading to More Glass Breakage

## 1. Module Design

- More than 80% of all modules manufactured now are glass/glass
- Module size has more than doubled in last 10 years
- Three junction box holes at module centre, instead of one at the top
- Mounting holes still at same distance leading to higher bending stresses
- Frame width and thickness shrinking

- Less rigid
- Load bearing
- Higher stresses



## Factors Leading to More Glass Breakage

### 2. Glass Quality

- Glass/backsheet modules used 3.2mm fully tempered glass
- High flexural strength and a larger range of temperature resistance
- Glass/glass modules currently on the market are using 2mm heat strengthened glass
- 50% lower bending strength and temperature resistance



➤ Weaker
➤ More sensitive to impact
➤ More sensitive to operational loads

Material	Flexural strength	Temperature change resistance
Float glass	45 N/mm <sup>2</sup>	40 K
Heat strengthened glass	70 N/mm <sup>2</sup>	100 K
Tempered glass	120 N/mm <sup>2</sup>	200 K

## Factory Findings

Manufacturing defects can be identified during independent Pre-shipment Inspection (PSI)

- Directly impacting glass breakage risk
  - Glass damage
  - Frame assembly
  - Sealant



[www.kiwa.com/  
pvqualityreport](http://www.kiwa.com/pvqualityreport)




Figure 11. The distribution of defects identified during PSI



# Lab Tests and Findings

## Thickness

- Glass thickness not as expected:
  - tolerance of **+/-0.2 mm** is too large
  - should be tightened to **-0/+0.2 mm**

## Inhomogeneity of Surface Compression



- Surface compression on 2 mm rear side glass:  
-64 to -117 N/mm<sup>2</sup> determined over four modules
- SCALP, ASTM C1279-13 (2019)  
*Standard Test Method for Non-Destructive Photoelastic Measurement [...] in Glass*




# Lab Tests and Findings

## Cross-section-cut analysis

- Glass thickness measurement
- Sealant quality
- Even distribution of sealant



Silicone (or gap)  
thickness  
@ long side



## Lab Tests and Findings

### Static and dynamic mechanical load testing


- 2025 PV Module Reliability Scorecard ([www.scorecard.pvel.com](http://www.scorecard.pvel.com)) results showed:
  - 20% of BOMs undergoing the PQP's Mechanical Stress Sequence (MSS) experience broken glass or frames
  - 40% of manufacturers experienced at least one failure during MSS testing



## Field Findings

### Incompatibility Between Module and/ or Mounting Support



- On-site inspection:
  - Incorrect module mounting holes used
  - Torque level too high or too low
  - Unstable foundations




## Field Findings

### Impact from flying objects

- 6 to 27% of the broken modules show **clear signs of impact**, but many others not obvious
- Some evidence of thrown stones and mud, one case (E) clearly from cleaning device
- Microscopic validation of impact is important



## Summary of Potential Causes



# Action Plan for the Industry

## 1. Prevention before Production

- Glass specifications (e.g. positive tolerance)
- Quality requirements in MSA and during audit
- Extended reliability testing
- Verifying operational loading vs. test loading

## 2. Control during Production

- Incoming goods verifying specs and quality
- Production oversight (e.g. framing, sealant, dimensions, glass cutting)
- Lab testing samples (e.g. frame cutting, SCALP, dimensions)

## 3. Oversight during Construction and Operations

- Inspection of foundation installation
- Verifying of module mounting position and torques
- Improving O&M activities (e.g. grass cutting with cover, limiting vehicle speeds)

## 4. Near to Mid Term Industry Requirements

- Updated testing standards and protocols (e.g. in-plane forces, rear-side impact test)
- Definition of advanced glass quality specifications (e.g. heat strengthening, impact resistance)
- Specify design loads and safety factors sufficient for operational stresses

**Solar glass must be made fit for purpose again**



Steven Xuereb, Executive Director

[Steven.Xuereb@kiwa.com](mailto:Steven.Xuereb@kiwa.com)

2 December 2025

**kiwa**